

- Patented vibratory feed system for uniform media flow and precise control
- Intermittent or continuous duty capability
- Heavy duty construction
- o Pinch valve shutoff with wear detector
- Long life fittings at critical wear points

The AIRBRASIVE® Model H gives high volume producers the ability to micro blast parts on production lines or in labs. This sturdy machine has been designed to accommodate both intermittent (foot switch activated) or continuous operations.

Powder flow lines are reinforced with tungsten carbide fittings for the utmost reliability in a continuous operation. It utilizes our patented vibratory feed for uniform powder flow. Powder flow is adjusted via our powder flow and pressure controls on the front panel.

Added to this machine is an auxiliary powder chamber monitored for powder level. Once it falls below a certain level, an indicator light tells the operator to fill the auxiliary chamber with powder. This guarantees consistent powder flow for continuous operation.

# **AIRBRASIVE®** MODEL H

### SPECIFICATIONS

Voltage: 110 volt, 60Hz or 220V, 50Hz

Current: 1 amp

Pressure: Up to 140 psig

Minimum line press: 50 psig

Air Supply: 5 scfm (2.4 L/sec)

Chamber Capacity: 4 lbs. (1.8 kg) of powder

Powder Flow: Up to 40 grams/min

Orifice plate: 8 holes x 26 mil dia. (0.7mm)

Relief Valve Setting: 140 psig (9.8 kg/sq.cm)

Helght: 22.5" (57.2 cm)

Width: 14.75" (38.0 cm)

Depth: 9.63" (25.0 cm)

Welght: 60 lbs. (27.2 kg)

#### STANDARD ACCESSORIES

Foot switch and 6 ft of hose

Handpiece and 6 ft of hose

Air Supply Hose (5 ft)

Nozzle (0.18" ID, straight)

Nozzle (0.18" ID, right angle)

AccuBRADE 27 Aluminum Oxide Powder (27 micron, 4 LBS)

AccuBRADE 50 Aluminum Oxide Powder (50 micron, 4 LBS)

#### RECOMMENDED ACCESSORIES

Work Chamber, 110V or 220V

Dust Collector, bag type or cartridge type, ¾ HP, 110V or 220V

Air / Oil Filter

## Airbrasive Jet Technologies, LLC